

**Please be aware that the following fixing bolts on ALL
Sprinter and 2006 CO Drills have changed**

Bottom Plate Changes

Previous fixings for Bottom Plates

HO-00360120 - Bottom Plate Rtg Bolt
HO-33010103 - Bottom Plate Rtg Nut

New Bottom Plate Fixings

HO-00360410 - Bottom Plate Rtg bolt
HO-33010103 - Bottom Plate Rtg Nut (remains the same)

Coulter Point Changes

Previous fixings for Coulter Points

HO-00370233 - Point Rtg Pin

New Fixings for Coulter Points

HO-00360031 - Point Rtg Bolt
HO-00350081 - Point Rtg Bolt Nut

Kevin Waddingham
Parts Manager

Tel: (01529) 301207

email: kevin.waddingham@simba.co.uk